

XIM Peel Bond



Premium repaint of classic home in Shaker Heights, OH - 2005

Condition- Several layers of old paint, replacement cedar shingles

Contractor- Sustaric Painting and Decorating

Finish topcoat- Sherwin Williams Durations

Peel Bond challenge- blend old and new section to present a smooth uniform appearance



XIM Peel Bond

Home in Shaker Heights, OH - 2005

After Refinishing

